

YVEA Inspections of Customer Installed Service Conduit

YVEA now requires that all customer-installed service conduit be inspected by YVEA prior to backfilling the trench. YVEA will no longer pull service wire into any conduit for which we do not have an inspection record on file.

To avoid unnecessary delays in having your service conduit inspected by YVEA, make sure you have done the following:

Install the entire conduit run in the trench.

This includes the stubs up to the meter enclosure and into the transformer, secondary pedestal, or riser pole.

DO NOT backfill the trench.

The YVEA inspector will require that the whole conduit run be installed and exposed before approving the installation.

Request a YVEA Inspection by contacting the YVEA dispatcher at:

871-2283 - Steamboat Springs Office
824-1483 - Craig Office

When requesting an inspection, you will be required to give:

- Your name
- Your Telephone Number
- The Residence Owner's Name
- Subdivision & Lot Number of Service Location
- Physical Address of Service Location

A YVEA Inspector will then contact you and tell you whether or not your installation has passed inspection, and what must be done if it has not passed inspection.

If your request for a conduit inspection is received by 3:30 p.m. on a business day YVEA will inspect the conduit sometime before the end of the next business day. (It may take us until sometime the second business day after your call if your project is more than 25 miles from the YVEA office.)

REVISIONS	DATE	DRAWN BY	CHECKED BY
		CLR	
		FILE	DATE
			3/26/01

YAMPA VALLEY ELECTRIC ASSC.
STEAMBOAT SPRINGS,
COLORADO

DS-4-6

INSPECTIONS OF CUSTOMER
INSTALLED SERVICE CONDUIT